Government of Karnataka
Public WorksDepartment

Office of the Executive Engineer, Mysore Division, Mysore
www.eemys@kpwd.gov.in Telephone No./ Fax No.: 0821 2420810

No.EE.PWD.Mys.Div.Mys:AE-1:BSC: 2022-23:No.781 08-06-22

To
Secretary
Diocesan Education Society,
Jayalakshmipuram, Mysore:

Sir

Sub: Regarding issuance of building safety certificate to St. Joseph's Central School Situated in Mysore City, Yelwal village.

Ref:1. Assistant Executive Engineer, Public WorksDepartment, No.1, Subdivision, Mysore, their office letter No.335 dated 06.06.2022.
2. Govt. letter No. (Education Department) PWD 59 BED 2019 dated 6-5-2022.

Regarding the above subject matter, in reference letter Secretary, Diocesan Education Society, Jayalakshmipuram, they have requested to issue building safety certificate for the school building of St. Joseph's Central School, Yelwal Village, Mysore which is under their authority. Regarding the said matter, in the prescribed form as per ref. (1) Assistant Executive Engineer, Public Works Department No.1 Sub Division, Mysore has submitted.

St. Joseph's Central School, Yelwal Village, Mysore School Building has been given Structural Stability Certificate by Executive Engineer, PWD, Mysore Division, Mysore and Assistant Executive Engineer, No.1 Sub Division, Mysore, Assistant Executive Engineer, Quality Assurance Sub Division, Mysore. Sri.R.Syed Khader, R.S. Consultants, BCCBL-3.6.SE 33:07-08 along with Structural Design and technical reports in the prescribed form has submitted the report. The said report on spot verified in ref.(2) Assistant Executive Engineer, Public Works Department, No.1 Sub-Division, Mysore has certified.

The said building verified is being constructed and completed in 2007. The building consists of ground floor, first floor and second floor. Sri. R Syed Khader, R.S. Consultants, BCC /BL-3.6/SE-33:07-08 has certified that the building is safe and has all kinds of facilities.

Further, regarding the safety of the building, Assistant Executive Engineer, No.1, Sub DivisionMysore in reference letter regarding concrete strength of the building dated 04.04 2022 Assistant Executive Engineer, quality control, Sub Division, Mysore, and Sri. R Syed Khader, R.S. Consultants BCC/BL-3.6/SE-33:07-08 have carried out their Physical observation & Accordingly necessary field Tests have been conducted and reported that the building is found to be sound as per the test report. As per the Sub-division Technical Section and Consultants.

Kannada Text translated to English
By Dr Vijayalakshmi A Patil

PRINCIPAL
ST. JOSEPH'S CENTRAL SCHOOL
Mysore-Hunsur Road, Yelwal Post
Mysore Dist - 577 120

Secretary
St. Joseph's Central School
Mysore Hunsur Road, Yelwal, Mysore

- Recognizance, visual inspection of building-cracks, distress, dampness etc., tests along with Sri. R Syed Khader, R.S. Consultants. BCC/BL-3.6/SE-33:07-08and Technical Team of Public Works Department has been conducted. In that it is observed re-examination after rectifying the deficiencies noted in them found that the building is of good quality.

- Form for Certificate for Structural Design Sufficiency has been issued by Sri. R Syed Khader, R.S. ConsultantsBCC/BL-3.6/SE-33:07-08.

As per the Government of Karnataka Circular No. PWD:59:BED:2019 Dated 06:05 2012, to obtain the building safety certificate prescribed fee of Rs. 1,000/ has been paid to the Accounts Head, on 8-6-2022, all the documents provided by the saidInstitute being verified the Assistant Executive Engineer, Quality control, Sub Division, Mysore, Sri R Syed Khader, RS Consultants, BCC/BL-3.6/SE-33:07-08 Building. Considering the certificate given that it is structurally safe and the building has been inspected by the technical team of the Public Works Department, it has been found from the test reports that the building is structurally stable. Hence for the current academic yearBuilding Safety Certificate has been issued.

Yours faithfully,
Sd/-
Executive Engineer
Public Works Department,
Mysore Division Mysore

PRINCIPAL
ST. JOSEPH'S CENTRAL SCHOOL
Mysore-Hunsur Road, Yelwal Post
Mysore Dist - 577 130

Secretary
St. Joseph's Central School
Mysore Hunsur Road, Yelwal, Mysore

ಕರ್ನಾಟಕ ಸರ್ಕಾರ

B-6.

ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್‌ರವರ ಕಛೇರಿ, ಮೈಸೂರು ವಿಭಾಗ, ಮೈಸೂರು.

ದೂರವಾಣಿ ಸಂಖ್ಯೆ/ಫ್ಯಾಕ್ಸ್ ನಂ: 0821 2420810

www:eemys@kpwd.gov.in

ಸಂ:ಕಾಇಂ:ಲೋಇ:ಮೈವಿಮೈ:ಸ ಇಂ-1:ಸುಪ್ರಪ:2022-23: NO 781 08-06-22

ರವರಿಗೆ

ಕಾರ್ಯದರ್ಶಿಗಳು,
ಡಯೋಸಿಸನ್ ಎಜುಕೇಷನ್ ಸೊಸೈಟಿ,
ಜಯಲಕ್ಷ್ಮೀಪುರಂ,
ಮೈಸೂರು

ಮಾನ್ಯರೇ,

ವಿಷಯ: ಮೈಸೂರು ನಗರ ಇಲವಾಲ ಗ್ರಾಮದಲ್ಲಿರುವ ಸೈಂಟ್ ಜೋಸೆಫ್ಸ್ ಸೆಂಟ್ರಲ್ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವ ಬಗ್ಗೆ.

ಉಲ್ಲೇಖ 1. ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.1ನೇ ಉಪವಿಭಾಗ, ಮೈಸೂರು. ಇವರ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ 335 ದಿನಾಂಕ 06.06.2022.

2. ಸರ್ಕಾರದ ಪತ್ರ ಸಂಖ್ಯೆ (ಶಿಕ್ಷಣ ಇಲಾಖೆ) ಲೋಇ:59:ಜಿಇಡಿ:2019 ದಿನಾಂಕ 06.05.2022.

***

ಮೇಲಿನ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಉಲ್ಲೇಖ ಪತ್ರದಲ್ಲಿ ಕಾರ್ಯದರ್ಶಿಗಳು, ಡಯೋಸಿಸನ್ ಎಜುಕೇಷನ್ ಸೊಸೈಟಿ, ಜಯಲಕ್ಷ್ಮೀಪುರಂ. ರವರು ತಮ್ಮ ಅಧೀನದಲ್ಲಿರುವ ಸೈಂಟ್ ಜೋಸೆಫ್ಸ್ ಸೆಂಟ್ರಲ್ ಶಾಲೆ, ಇಲವಾಲ ಗ್ರಾಮ, ಮೈಸೂರು ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲು ಕೋರಿದ್ದು, ಸದರಿ ವಿಚಾರಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ನಿಗದಿತ ನಮೂನೆಯಲ್ಲಿ ಉಲ್ಲೇಖಿತ ಪತ್ರ (1) ರಲ್ಲಿ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.1ನೇ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ಇವರು ಸಲ್ಲಿಸಿರುತ್ತಾರೆ.

ಸೈಂಟ್ ಜೋಸೆಫ್ಸ್ ಸೆಂಟ್ರಲ್ ಶಾಲೆ, ಇಲವಾಲ ಗ್ರಾಮ, ಮೈಸೂರು ಶಾಲೆಯ ಕಟ್ಟಡವನ್ನು ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ಲೋಇ., ಮೈಸೂರು ವಿಭಾಗ, ಮೈಸೂರು ಹಾಗೂ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.1 ಉಪವಿಭಾಗ, ಮೈಸೂರು ರವರು ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಗುಣಭರವಸೆ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು Structrual Stability Certificate ನೀಡಿದ್ದು, Sri. R Syed Khader, R.S. Consultants, BCC/BL-3.6/SE-33:07-08 ರವರು Structrural Design ಹಾಗೂ ತಾಂತ್ರಿಕ ವರದಿಗಳೊಂದಿಗೆ ನಿಗದಿತ ನಮೂನೆಯಲ್ಲಿ ವರದಿಯನ್ನು ಸಲ್ಲಿಸಿರುತ್ತಾರೆ. ಸದರಿ ವರದಿಯನ್ನು ಸ್ಥಳ ಪರಿಶೀಲಿಸಿ ಉಲ್ಲೇಖ (2) ರಲ್ಲಿ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.1ನೇ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು ದೃಢೀಕರಿಸಿರುತ್ತಾರೆ.

ಸದರಿ ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ, ಕಟ್ಟಡವನ್ನು 2007 ರಲ್ಲಿ ನಿರ್ಮಾಣಗೊಂಡು ಪೂರ್ಣಗೊಂಡಿರುತ್ತದೆ. ಕಟ್ಟಡವು ನೆಲಮಹಡಿ, ಮೊದಲನೇ ಮಹಡಿ ಮತ್ತು ಎರಡನೇ ಮಹಡಿಯನ್ನು ಒಳಗೊಂಡಿರುತ್ತದೆ. Sri. R Syed Khader, R.S Consultants, BCC/BL-3.6/SE-33:07-08 ರವರು ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿರುವ ಬಗ್ಗೆ ಹಾಗೂ ಎಲ್ಲಾ ರೀತಿಯ ಸೌಲಭ್ಯಗಳನ್ನು ಹೊಂದಿರುವ ಬಗ್ಗೆ ದೃಢೀಕರಿಸಿರುತ್ತಾರೆ.

ಮುಂದುವರೆದು, ಕಟ್ಟಡದ ಸುರಕ್ಷತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.1 ಉಪವಿಭಾಗ, ಮೈಸೂರು ರವರು ಉಲ್ಲೇಖಿತ ಪತ್ರದಲ್ಲಿ ಕಟ್ಟಡದ ಕಾಂಕ್ರೀಟ್ ಸಧೃಢತೆಯ ಬಗ್ಗೆ ದಿನಾಂಕ: 04.04.2022 ರಂದು ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಗುಣಭರವಸೆ ಉಪವಿಭಾಗ, ಮೈಸೂರು, and Sri. R Syed Khader, R.S. Consultants, BCC/BL-3.6/SE-33:07-08 made Physical observation & Accordingly necessary field Tes

PRINCIPAL
ST. JOSEPH'S CENTRAL SCHOOL
Mysore-Hunsur Road, Yelwal Post
Mysore Dist - 577 130

Secretary
St. Joseph's Central School
Mysore Hunsur Road, Yelwal, Mysore

ಪರೀಕ್ಷೆಗಳನ್ನು ಕೈಗೊಂಡು, ಸಮಾಲೋಚಕರೊಂದಿಗೆ ಉಪವಿಭಾಗದ ತಾಂತ್ರಿಕ ವರ್ಗವು ನಡೆಸಿರುವ ಪರೀಕ್ಷೆಯ ವರದಿಯಂತೆ ಕಟ್ಟಡವು ಸದೃಢತೆಯಿಂದ ಇರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ ಎಂದು ವರದಿ ಮಾಡಿರುತ್ತಾರೆ.

- Recognizance, visual inspection of Building-cracks, distress, dampness etc. ಪರೀಕ್ಷೆಯನ್ನು **Sri. R Syed Khader, R.S. Consultants, BCC/BL-3.6/SE-33:07-08** ರವರ ಜೊತೆ ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ತಾಂತ್ರಿಕ ತಂಡದೊಂದಿಗೆ ಕೈಗೊಳ್ಳಲಾಗಿರುತ್ತದೆ. ಅದರಲ್ಲಿ ಗಮನಿಸಲಾದ ನ್ಯೂನತೆಗಳನ್ನು ಸರಿಪಡಿಸಿದ ನಂತರ ಮರು ಪರೀಕ್ಷೆಯಲ್ಲಿ ಕಟ್ಟಡವು ಉತ್ತಮ ಗುಣಮಟ್ಟದಿಂದ ಕೂಡಿರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ.
- Form for Certificate for Structural Design Sufficiency ಪ್ರಮಾಣ ಪತ್ರವನ್ನು **Sri. R Syed Khader, R.S. Consultants, BCC/BL-3.6/SE-33:07-08** ರವರು ನೀಡಿರುತ್ತಾರೆ.

ಸದರಿ ಸಂಸ್ಥೆಯವರು ಕರ್ನಾಟಕ ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ ಲೋಇ:59:ಬಿಇಡಿ:2019 ದಿನಾಂಕ 06.05.2022. ರಂತೆ ಸದರಿ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪಡೆಯಲು ನಿಗದಿಪಡಿಸಿರುವ ಶುಲ್ಕವಾದ ರೂ. 1,000.00 ಗಳನ್ನು ದಿನಾಂಕ 08.06.2022 ರಂದು ಲೆಕ್ಕಶಾಖೆಗೆ ಪಾವತಿಸಿರುತ್ತಾರೆ. ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ **ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜನಿಯರ್, ಗುಣಭರವಸೆ ಉಪವಿಭಾಗ, ಮೈಸೂರು, Sri. R Syed Khader, R.S. Consultants, BCC/BL-3.6/SE-33:07-08** ರವರು ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪರಿಗಣಿಸಿ, ಹಾಗೂ ಕಟ್ಟಡವನ್ನು ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ತಾಂತ್ರಿಕ ತಂಡ ಪರಿಶೀಲಿಸಲಾಗಿ ಕಟ್ಟಡವು **"Structurally Stable"** ಇರುವುದಾಗಿ ಪರೀಕ್ಷಾ ವರದಿಗಳಿಂದ ಕಂಡುಬಂದಿರುವುದರಿಂದ ಪ್ರಸಕ್ತ ಶೈಕ್ಷಣಿಕ ಸಾಲಿಗೆ ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು (Building Safety Certificate) ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಕಾರ್ಯಪಾಲಕ ಇಂಜನಿಯರ್
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ
ಮೈಸೂರು ವಿಭಾಗ, ಮೈಸೂರು.

PRINCIPAL
ST. JOSEPH'S CENTRAL SCHOOL
Mysore-Hunsur Road, Yelwal Post
Mysore Dist - 577 130

Secretary
St. Joseph's Central School
Mysore Hunsur Road, Yelwal, Mysore